

Oil Field Environmental Incident Summary

Incident: 20160630113206 **Date/Time of Notice:** 06/30/2016 11:32

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: PEDERSON 3

Field Name: TEMPLE

Well File #: 9361

Date Incident: 6/30/2016

Time Incident: 10:45

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 18

Qtr:

Location Description:

Submitted By: Scott Hunskor

Received By:

Contact Person: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	6	Barrels	6	Barrels	6	barrels
Brine	4	Barrels	4	Barrels	4	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/12/2016

Clean Up Concluded: 7/5/2016

Risk Evaluation:

none

Areal Extent:

Any accumulation was contained on well site and area of mist on cropland is approximately 60' x 80'

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut well in and secure well head, make sure fluid on location is contained. Scrape up affected area down to clean soil and haul away and replace with acceptable material. Install a well head dome catcher with well shut off.

Wastes Disposal Location: PDI

Agencies Involved: ND dept. of health by state inspector.

Updates

Date: 6/30/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 5:30, 6/30/2016.

Workers on scene scraping up soil that was impacted to the west. There are remaining impacts to areas off of location. The spill did drain slightly to the east of the well location, but it didn't impact areas off of location.

More follow-up is necessary to ensure proper cleanup.

Date: 6/30/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained to the well pad. Further follow-up is needed.

Date: 7/26/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/26/2016 at 13:35, on location. Area south/southwest of wellhead has been covered in new topsoil where impacted soil was scraped. Vegetation growing in new topsoil. Impacted area was originally flax, and in certain spots some flax can be seen growing up through the new topsoil. No further follow-up required at this time.